

BILL NO. S-76-07-19

SPECIAL ORDINANCE NO. S-134-76

AN ORDINANCE approving two invoices of Bercot-Gibson Construction Co., Inc. for emergency repairs of sanitary sewers at Delaware Avenue and Spy Run.

BE IT ORDAINED BY THE COMMON COUNCIL OF THE CITY OF FORT WAYNE, INDIANA:

SECTION 1. The invoices of Bercot-Gibson Construction Co., Inc., approved June 8, 1976, by the City of Fort Wayne, by and through its Mayor and the Board of Public Works, for emergency repairs of the sewer at 1718 Delaware Avenue, in the amount of \$7,627.40, and at 1317 Spy Run, in the amount of \$4,071.93, for a total sum of \$11,699.33, are hereby in all things ratified, confirmed and approved.

SECTION 2. This ordinance shall be in full force and effect from and after its passage and approval by the Mayor.


Councilman

APPROVED AS TO FORM
AND LOCALITY


CITY ATTORNEY

Read the first time in full out in session by _____ recorded for
Mayor and duly adopted that the amount due by and to be returned
 to the Executive on Public Works and the City of New Orleans for
 communication and public works to the city and the City of New Orleans
 Officers, City Council, Building, and Public Works, and the City of
 at _____ 1901 and _____ of the City of New Orleans

DATE July 10 1901 Mayor

Read the first time in full out in session by Mayor
 recorded by Mayor and duly adopted placed on the grounds
 that it is by the following:

	APPROVED	APPROVED	APPROVED	APPROVED	APPROVED
TOTAL AMOUNT	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
RECEIVED	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
PAID	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

DATE July 10 1901 Mayor

Read and adopted by the Council of the City of New Orleans, and the
 to the City of New Orleans, and the City of New Orleans, and the City of New Orleans

and the City of New Orleans, and the City of New Orleans, and the City of New Orleans
 and the City of New Orleans, and the City of New Orleans, and the City of New Orleans

and the City of New Orleans, and the City of New Orleans, and the City of New Orleans
 and the City of New Orleans, and the City of New Orleans, and the City of New Orleans

Approved and signed by me this _____ day of _____ 1901
 at the City of _____

Mayor

Bill No. S-76-07-19

REPORT OF THE COMMITTEE ON PUBLIC WORKS

We, your Committee on Public Works to whom was referred an Ordinance
approving two invoices of Bercot-Gibson Construction Co., Inc. for
emergency repairs of sanitary sewers at Delaware Avenue and Spy Run

have had said Ordinance under consideration and beg leave to report back to the Common
Council that said Ordinance DO PASS.

Winfield C. Moses, Jr. - Chairman

Donald J. Schmidt - Vice-Chairman

Vivian G. Schmidt

Paul M. Burns

William T. Hinga

Winfield C. Moses, Jr.

Donald J. Schmidt

Vivian G. Schmidt

Paul M. Burns

William T. Hinga

DATE 7-27-76 CONCURRED IN
CHARLES W. WESTERMAN, CITY CLERK

Memorandum

To BOARD OF PUBLIC WORKS

Date June 11, 1976

From Philip R. Boller, P.E.

Subject Emergency Sewer Repair on Delaware Street

COPIES TO:

Per the attached directive from the General Superintendent.

For your review and action, please find attached an invoice from Bercot-Gibson Construction Co., Inc. in the amount of \$7,627.40 which is the total cost for this emergency repair. Their claim is also attached.

We feel that all the required emergency repair work has been completed satisfactorily and therefore, recommend payment. We are also sending copies of the following documents for support of this payment.

1. Emergency Sewer Repair Inspection Reports.
2. Sketch of repair

Philip R. Boller

Philip R. Boller, P.E.
Chief Water Pollution Control Engineer

PRB/lmm

P.S. Payment of this invoice should be made from City Utilities funds.


PRB

NOTED

H.P.W.

☐ E.H.L.
☐ M.G.S.

Date _____



Council 6-15-76

BERCOT-GIBSON CONSTRUCTION CO., INC.

Excavating - Sewers & Grading

OFFICE PHONE 484-3120

3838 MOBILE AVENUE

FORT WAYNE, INDIANA 46805

June 8, 1976

Board of Public Works
City Utilities
City of Fort Wayne
Fort Wayne, Indiana

Job: Emergency Sewer repair
Delaware Street
March 5,8,9,10,11,15,
April 2,5,6,8,28

	Materials	Rented Equipment
Concrete Saw rental		67.60
3" Pump rental & hoses		39.52
Henderson Reed - Burlap Bags	3.60	
Midwest Aggregates - 17.05 T #2 Stone	60.53	
Old Fort Concrete	54.30	
Construction Products Corporation - 23" pipe & Manhole	647.50	
Treaty Company - Casting & lid	89.00	
Stonestreet Gravel, Inc. - 141.70 Ton #73 & #2 Stone	368.42	
Kowak & Williams - Barricade Rental		18.72
Irving Ready Mix - 154 yd Concrete	376.30	
Old Fort Supply - Expansion joints	8.25	
Old Fort Supply - Curing Compound	48.30	
Old Fort Supply - 2 ft of 6" C Ring sewer pipe	2.50	
Old Fort Supply - 1 - 6" O Ring Saddle	7.50	
Old Fort Supply - 1 - 6" 22 deg. Ell	7.50	
Old Fort Supply - 10 gal. Tri-Mix	19.00	
Old Fort Supply - 2 sx Portland Cement	6.30	
Old Fort Supply - 3 sx Speedcrete	23.85	
Old Fort Supply - 6 ft of 12" O Ring	23.10	
Old Fort Supply - 6 ft of 15" O Ring	43.50	
Old Fort Supply - 6 ft of 15" VC Sewer	49.50	
Old Fort Supply - 1 sx Speedcrete	7.95	
Old Fort Supply - 1 sx Concrete Mix	9.00	
Bercot-Gibson Yard - 8 bags Sandmix	12.40	
Bercot-Gibson Yard - 4 bags Mortar mix	11.00	
Bercot-Gibson Yard - 1 foot of Manhole rings	12.75	
	<u>1,892.05</u>	<u>125.64</u>
		1,892.05
		2,017.89
	+ 11% O.H. & Taxes	221.97
		<u>2,239.86</u>
25 1/2 hr American Crane & operator @ 48.25		268.78
2 hr Ford Concrete Breaker & operator @ 34.75		2,508.64
8 hr rubber tired hydraulic hoe & operator @ 28.75		1,230.38
3 1/2 hr Tandem dump truck & driver @ 28.25		69.50
11 hr Michigan Loader & operator @ 37.25		226.00
7 hr Tri axle Dump truck & driver @ 30.75		946.38
Laborers - 130 manhours @ 15.55		409.75
		<u>2,215.25</u>
		<u>2,021.50</u>
		7,627.40

APPROVED
Deird of Public Works

Profit

Handwritten signatures and notes:
P. P. [unclear]
[unclear]
[unclear]
[unclear]

LOCATION: 1718 DELAWARE

B. Q. NO.: _____

EMERGENCY SEWER REPAIRS INSPECTION REPORT

CONTRACTOR BERCOT STARTING TIME AND DATE 9:00 A.M. 3-15-76

CONTRACTOR		PERSONNEL	CONTRACTORS	EQUIPMENT
	NO.	HRS. WRKD.	TYPE AND SIZE	HRS. USED
SUPERVISION				
OPERATORS				
LABORERS	2	1	Two MEN WORKED ON M.H. INVERT	

MATERIALS USED

DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)
<u>MATERIALS FROM BERCOT STOCK</u>	
<u>5" SAND MIX</u>	<u>8 BAGS</u>
<u>MORTAR MIX</u>	<u>4 "</u>
<u>MANHOLE RINGS</u>	<u>1 FT.</u>

INSPECTORS EVALUATION

TYPE OF SURFACE ASPHALT CONCRETE DIRT


DEPTH OF SEWER SIZE TYPE

SOIL CONDITIONS CLAY SAND GRAVEL WET DRY

CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD POOR

POSSIBLE CAUSE OF FAILURE: _____

COMPLETION DATE AND TIME _____



INSPECTORS SIGNATURE

LOCATION: 1718 DELAWARE
 B. O. NO.: _____

EMERGENCY SEWER REPAIRS INSPECTION REPORT

CONTRACTOR BERCOT STARTING TIME AND DATE 8:00 AM 3-11-76

CONTRACTOR	PERSONNEL	CONTRACTORS EQUIPMENT
	NO. HRS. WRKD.	TYPE AND SIZE
SUPERVISION	1 8	MICH. LOADER
OPERATORS	1 4	
LABORERS	2 4	
1-LABOR	1 8.5	

MATERIALS USED

DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)
CEMENT MIX	4 - BAGS
SPIRAL CRESTLE	1 - BAG
#73 CRUSH STONE	27 TON
POURED INVERT & WROTE ON CLEAN-	
UP & RESTORATION OF ALLEY	

INSPECTORS EVALUATION

TYPE OF SURFACE _____ ASPHALT _____ CONCRETE _____ DIRT _____
 DEPTH OF SEWER _____ SIZE _____ TYPE _____
 SOIL CONDITIONS CLAY _____ SAND _____ GRAVEL _____ WET _____ DRY _____
 CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD _____ POOR _____
 POSSIBLE CAUSE OF FAILURE: _____

CONC. ALLEY HAS TO BE PAID BACK YET

COMPLETION DATE AND TIME _____

Inspector
 INSPECTORS SIGNATURE

LOCATION: 1718 DELAWARE

B.O. NO.: _____

EMERGENCY SEWER REPAIRS
INSPECTION REPORTCONTRACTOR PERCOTSTARTING TIME AND DATE 8:00 A.M. 3-20-71

CONTRACTOR PERSONNEL			CONTRACTORS EQUIPMENT	
	NO.	HRS. WRKD.	TYPE AND SIZE	HRS. USED
SUPERVISION	1	9	BACKHOE (AMERICAN)	9
OPERATORS	1	9	TANDEM TRUCK	9
LABORERS	2	9	MICH. LOADER	9
TRUCK DRIVER	1	9	CONC. SAW (RENTAL)	9
			3" PUMP	4

MATERIALS USED


DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)
TRIMIX	10 GAL
SPEED CURE	3 BAGS
CEMENT	2 "
73 CRUSH STONE 7 LOADS	219.200
THERE WAS 10' OF NEW 24" PIPE LAYED	
SOUTH OF M.H. & 5' OF NEW 24" PIPE LAYED	
NORTH OF M.H.	
SEWER MAINTANCE SUPPLIED 1-3" PUMP TODAY 7 HRS	

INSPECTORS EVALUATION

TYPE OF SURFACE _____ ASPHALT _____ CONCRETE ✓ DIRTDEPTH OF SEWER 12' SIZE 24" TYPE VITSOIL CONDITIONS CLAY _____ SAND ✓ GRAVEL _____ WET ✓ DRY _____CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD ✓ POOR _____

POSSIBLE CAUSE OF FAILURE: _____

COMPLETION DATE AND TIME _____


 INSPECTOR'S SIGNATURE

LOCATION: 1718 McLAWARE

B. Q. NO.: _____

EMERGENCY SEWER REPAIRS
INSPECTION REPORTCONTRACTOR BERCOTSTARTING TIME AND DATE 8:00 AM 3-9-76

CONTRACTOR PERSONNEL			CONTRACTORS EQUIPMENT	
	NO.	HRS. WKD.	TYPE AND SIZE	HRS. USED
SUPERVISION	1	8	BACKHOE (AMERICAN)	8
OPERATORS	1	8	TANDEM TRUCK	8
LABORERS	2	8	MICH. COALERS	8
TRUCK DRIVER	1	8	TANDEM TRUCK + DRIVER (BUNSON)	4
			CGNC. SAW (RENTAL)	4


MATERIALS USED

DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT. YD. TONS, ETC.)
4 - 24" X 7.5' RCP CLASS III	20'
1 - 48" M.H. + BASE	18' OF STACK
2 - COALS #2 STONE	71.200
6 - BURLAP BAGS	
4 - ORING VIT SEWER TILE 1-SAILOR 2-DECAIR	
THEY REMOVED THE M.H. + BROKEN	
TILE TODAY + LAYED 1-76" PIPE	

INSPECTORS EVALUATION

TYPE OF SURFACE ASPHALT CONCRETE ☒ DIRTDEPTH OF SEWER 12' SIZE 24" TYPE VITSOIL CONDITIONS CLAY SAND ☒ GRAVEL WET DRY ☒CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD ☒ POOR _____POSSIBLE CAUSE OF FAILURE: M.H. SETTLED DOWN + BROKEINCOMING + OUTGOING 24" VIT TILE "ITS IS AN OLD SEWER"

COMPLETION DATE AND TIME _____



INSPECTOR'S SIGNATURE

LOCATION: 1718 DELAWARE

B.O. NO.: _____

EMERGENCY SEWER REPAIRS INSPECTION REPORT

CONTRACTOR B.F. PCOTSTARTING TIME AND DATE 8:00 AM 3-8-71

CONTRACTOR PERSONNEL			CONTRACTORS EQUIPMENT	
	NO.	HRS. WRKD.	TYPE AND SIZE	HRS. USED
SUPERVISION	1	8	BACKHOF AMERICAN	8
OPERATORS	1	8	TANDEM TRUCK	8
LABORERS	2	8		
TANDEM TRUCK	1	8		

MATERIALS USED


DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)
NO MATERIALS USED TODAY	
THEY DECIDED TO FIND OUT WHAT MATERIAL WAS NEEDED TO MAKE REPAIR	

INSPECTORS EVALUATION

TYPE OF SURFACE ASPHALT CONCRETE DIRTDEPTH OF SEWER 12' SIZE 24" TYPE VITSOIL CONDITIONS CLAY SAND GRAVEL WET DRYCONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD POOR

POSSIBLE CAUSE OF FAILURE: _____

COMPLETION DATE AND TIME _____


 INSPECTORS SIGNATURE

Memorandum

To _____

Date _____


From _____

Subject _____

17/8 DELAWARE

COPIES TO:

CONCRETE REPLACEMENT



BACKFILL Req'd

SAW Dr Req'd

NOT RESOLVED

Confidential
Not to be
distributed
outside
the
agency

BERGOT-GIBSON CONSTRUCTION CO., INC.

BOARD OF PUBLIC WORKS

Excavating - Sewers & Grading

OFFICE PHONE 484-3120

3838 MOBILE AVENUE

FORT WAYNE, INDIANA 46805

June 8, 1975

Board of Public Works
City Utilities
City of Fort Wayne
Fort Wayne, Indiana

Job: Emergency Sewer repair
Spy Run Avenue
April 6,7,8,13,14,16

	<u>Materials</u>	<u>Rented Equipment</u>
Nowak & Williams - Barricade rental		9.93
Roethe Bldg. Materials-Lumber to move garage	284.09	
Schlatter Hardware - Small Tools	10.16	
Stone-Street Gravel, Inc. - 12.95 T #9 Stone	34.97	
Stone-Street Gravel, Inc. - 112.55 T Bank Gravel	140.69	
Stone-Street Gravel, Inc. - 47.10 T #73 Stone @ 2.60	122.47	
Wayne Pipe & Supply Co. - Jute Packing	1.84	
Keane Bros. Trucking-Haul 73.9 T Backfill		107.15
Old Fort Supply Co. - 2 - 12x6 VC Tee	45.50	
Old Fort Supply Co. - 9 ft of 12" VC Sewer pipe	29.25	
Old Fort Supply Co. - 4 - 6" Fittings	30.00	
Old Fort Supply Co. - 18 ft of 6" Wedgelok pipe	22.50	
Old Fort Supply Co. - 2 sx Sandmix	3.10	
3" Pump rental & hoses		
	<u>724.57</u>	39.52
		156.66
		724.57
		881.23
	+11% OH & Taxes	96.24
		976.17
	+12% Profit	117.38
		1,095.55
1½ hr Case 880 Hydraulic hoe(tracks) & operator @ 43.00		752.50
2 hr Tri Axle Dump truck and driver @ 30.75		61.50
2½ hr Tandem Dump trucks and drivers @ 28.25		607.38
Laborers - 100 manhours @ 15.55		1,555.00
		\$ 4,071.93

APPROVED
Board of Public Works

Henry A. Weisberg
Eric W. Carter
May G. Acott

LOCATION: 1317 SPYRUN

B. O. NO.: _____

EMERGENCY SEWER REPAIRS
INSPECTION REPORTCONTRACTOR BERCOTSTARTING TIME AND DATE 7:00 4/13/76

CONTRACTOR	PERSONNEL		CONTRACTORS	EQUIPMENT
	NO.	HRS. WRKD.	TYPE AND SIZE	HRS. USED
SUPERVISION			BACKHOE - CASE 820	11
OPERATORS	1	11	3" PUMP	4
LABORERS	3	11	LAST: 2 TANDAM TRUCKS & DRIVERS	
			(4 VES. 1 W/3. 1/2 RS.	
			(3 1/2 8 1/2 8 1/2	

MATERIALS USED

DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)
1 - 12" x 24" x 6" TEE VCP	
1 - 6" x 4" VCP	
3 - 12" x 24" VCP	
1 - 6" 45° ELBOW	

INSPECTORS EVALUATION

TYPE OF SURFACE ASPHALT CONCRETE X DIRT

DEPTH OF SEWER 13' SIZE 12" TYPE VCP

SOIL CONDITIONS CLAY SAND X GRAVEL WET DRY X

CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD POOR X

POSSIBLE CAUSE OF FAILURE: GARGE FLOOR SECTE CAVED IN FROM
REPAIR OF 16" HOUSE TAP WHICH WAS REPAIRED DO TO
MAIN COLADSE. 8' OF 12" VCP MAIN WAS REPLACED ALONG
WITH 10' OF 6" TAP TO HOUSE. NOTE: HOUSE WAS MOVED
BACK FROM ORIGINAL FOUNDATION TO NEW ONE.

COMPLETION DATE AND TIME _____

INSPECTORS SIGNATURE _____

LOCATION: 1317 SPYGLASS

B.O. NO.: _____

EMERGENCY SEWER REPAIRS
INSPECTION REPORTCONTRACTOR PERCOTSTARTING TIME AND DATE 7:00 4/14/76

CONTRACTOR PERSONNEL			CONTRACTORS EQUIPMENT	
	NO.	HRS. WRKD.	TYPE AND SIZE	HRS. USED
SUPERVISION				
OPERATORS	1	6 1/2	BACKHOE - CASE 880	6 1/2
LABORERS	2	6 1/2	STANDARD LYLE DUMP TRUCK	6 1/2
TRUCK DRIVER	1	6 1/2		

MATERIALS USED

DESCRIPTION (TYPE, SIZE, ETC.)	AMOUNT (FT., YD., TONS, ETC.)

INSPECTORS EVALUATION

TYPE OF SURFACE _____ ASPHALT _____ CONCRETE X DIRTDEPTH OF SEWER 13' SIZE 12" TYPE VCPSOIL CONDITIONS CLAY _____ SAND X GRAVEL _____ WET _____ DRY X

CONDITION OF SEWER ABUTTING REPAIRED SECTION GOOD _____ POOR _____

POSSIBLE CAUSE OF FAILURE: _____

COMPLETION DATE AND TIME _____

INSPECTORS SIGNATURE _____

LUMBER - MILLWORK - BUILDERS SUPPLIES

N 34419

FT. WAYNE, IND.

197

OLD TO *East-Gibson*

DELIVER TO

BILLING ADDRESS

CUSTOMER'S
ORDER NO.PRICED BY *VMA*

C. O. D.

CHARGE *1*CREDIT OK'D BY *D*

CK QUANTITY

DESCRIPTION

FEET

PRICE

TOTAL

8

3/4 x 5/8 Lumber 300

8

*3/4 x 5/8 Lumber 300**Copy Run Job*

Invoice due 10th of month following date of purchase.

Regular Stock returned to good order will be credited
At invoice price less 10% No credit allowed on special

TOTAL SALE

TAX

OFFICE OF
BOARD OF PUBLIC WORKS



FORT WAYNE 2, INDIANA

B.O. 23-76

Date March 31, 1976

To Phil Boller, WPC Engineer

Subject EMERGENCY SANITARY SEWER REPAIR - 1317 Spy Run Avenue

Please consider this as Board authorization to direct Bercot, Inc. to make emergency repair on sanitary sewer at above location.

Henry P. Wehrenberg

Ethel H. LaMar

Max G. Scott

BOARD OF PUBLIC WORKS

es

NOTED

Signed _____

Reply: _____

June 11, 1976

Members of the Board:

☐ ERL

☐ MGS.

Date _____

BOARD OF PUBLIC WORKS

JUN 15 1976

Council
6/11/76
C.U.

For your review and action please find attached an invoice from Bercot-Gibson Construction Co., Inc. in the amount of \$4,071.93, which is the total cost for this emergency repair. Their claim is also attached.

We feel that all the required emergency repair work has been completed satisfactorily and therefore recommend payment. We are also sending copies of the following documents for support of this payment.

1. Emergency Sewer Repair Inspection Reports
2. Pictures of repair.

Respectfully submitted,

Philip R. Boller
Philip R. Boller, P.C.

Chief Water Pollution Control Engineer

PRB/lmm
att.

Signed _____

63-162-16 6/4/76


Memorandum

File

To Mr. Joseph F. Morreale

Date March 1, 1976

From John C. Moran - W.P.C. Maintenance Dept.

Subject Emergency Repair - 1718 Delaware Ave. 

COPIES TO:

RECEIVED

MAR 1 1976

Water Pollution Control Engr. Dept.
City-County Building, One Main St.
Ft. Wayne, Indiana 46802

Upon investigation of an alley cave-in it was discovered that a brick manhole, that was built in 1910, had deteriorated and should be replaced with a concrete precast manhole and a new casting. It was also found that two 18 inch vitrified tile to the south of the manhole were crushed and needed to be replaced. To the north of the manhole at least one 18 inch tile, and the inverts also need to be replaced.

This Department cannot repair this excavation because it is twelve to thirteen feet deep. Our backhoe can only dig up to 10 feet and it is too light to set a precast manhole. The alley will also have to be restored, so we suggest that a contractor be hired to do the job.

10:30AM 3/1/76


alley block off.

John C. Moran

1:45PM 3/1/76

OK per H. Weinberg
and Barrett-Dibson

John



TITLE OF ORDINANCE SPECIAL ORDINANCE - Invoices of Bercot-Gibson Const. for Emergency Sewer
Repairs
DEPARTMENT REQUESTING ORDINANCE BOARD OF PUBLIC WORKS

SYNOPSIS OF ORDINANCE During the months of March and April two sanitary sewer

cave-ins occurred which necessitated the hiring of a private contractor to make
the Emergency Repairs. Bercot-Gibson Construction Co., Inc. was called in, and
repairs were made at the following locations.

1718 Delaware Avenue

\$7,627.40

1317 Spy Run

4,071.93

The Water Pollution Control Maintenance Department are not equipped to handle
these type emergency repairs.

Work was supervised by the Water Pollution Control Engineering Department and
said work has met with their approval.

(SEE ATTACHMENTS)

EFFECT OF PASSAGE Payment to contractor

EFFECT OF NON-PASSAGE Inability to pay for work already done due to state of
emergency

MONEY INVOLVED (DIRECT COSTS, EXPENDITURES, SAVINGS) Total cost to Utility - \$11,699.33

ASSIGNED TO COMMITTEE

Ad of B Public Wks Jthm